

8 7 6 5 4 3 2 1

D

C





B

A

D

C

B



NOTES:

1. REMOVE ALL BURRS & SHARP EDGES
2. ENSURE SHAFT STRAIGHTNESS
3. TAPPED HOLES ON ENDS DO NOT HAVE TO LINE UP WITH OPPOSITE END

PROPRIETARY AND CONFIDENTIAL
THE INFORMATION CONTAINED IN THIS
DRAWING IS THE SOLE PROPERTY OF
HPCAT. ANY REPRODUCTION IN PART
OR AS A WHOLE WITHOUT THE WRITTEN
PERMISSION OF HPCAT IS PROHIBITED.

UNLESS OTHERWISE SPECIFIED:	
DIMENSIONS:	INCH
MATERIAL:	1045 Steel
FINISH:	See Notes
	DO NOT SCALE DRAWING

		High Pressure Collaborative Access Team at the Advanced Photon Source		TITLE:	
				Gate Axis	
NAME	DATE	DRAWN	ER	07-20-16	SIZE
COMMENTS:					REV
					A
SCALE: 1:1			WEIGHT:		SHEET 1 OF 1

8 7 6